

EXPERT



Reserve Services, Inc.

**Traditional Reserve Studies - Replacement Cost Valuations
Structural Integrity Reserve Studies - Milestone Inspections**

Replacement Cost Valuation Prepared For:

**Southeaster Condominium Association,
4841 Saxon Drive,
New Smyrna Beach, FL 32169**



Date Of Site Visit:

May 20, 2025



www.expertreserveservices.com

(386) 677-8886

(866) 480-8236

OFFICES

**Daytona Beach, West Palm Beach,
Coral Gables (Miami), St. Petersburg and Venice**

EXPERT RESERVE SERVICES, INC.

Expert Reserve Services, Inc. has been serving the needs of Florida Homeowner and Condominium Associations since 2002. We offer our services to the entire State. The company maintains an 'A' rating from the Better Business Bureau as well as membership in numerous Chambers of Commerce and numerous professional organizations.

Per your request an inspection of the property was completed to determine the cost to replace the structure, in its current condition, if a total loss was to occur. In the following pages you will find a detailed property valuation report using the CoreLogic valuation system and program and photographs of the property.

The intended user of this replacement cost report is the property owner or insured. The intended use is to evaluate the property, analyze and report the replacement cost for insurance purposes, excluding the site value, demolition cost, excavation, land improvements and equipment costs. The exclusions or additions are computed on the basis of items specifically included or excluded from the coverage by the policy and it's riders and endorsement. The additional expense incurred for demolition and/or debris removal is a paper cost of reconstruction and is the matter of the underwriting policy and has not been included in this Replacement Cost Report. This is not a real estate appraisal, but a replacement cost report utilizing the accepted CoreLogic insurance appraisal calculation system.

A traditional appraisal places a market resale value on a property - this is exclusively what it would cost to replace the structure.

COST APPROACH TO VALUE:

In the case of valuation for insurance purposes, there is no imputed depreciation, as the improvements, if destroyed would be replaced in full at the current value.

DEFINITION OF INSURABLE VALUE

The following definition is used for valuations:

1. The portion of the value or asset group that is acknowledged or recognized under the provisions of an applicable loss insurance industry.
2. Value used by insurance companies as the basis for insurance. Often considered to be replacement or reproduction cost less deterioration of non-insurable items.

Cost estimates are derived from CoreLogic software with the most recent updates available. Administrative and profit included in price per square foot estimates.



Southeaster Condominium Association

4841 Saxon Dr., New Smyrna Beach, FL 32169



- Insurance Replacement Cost Valuation -

Property Overview:

The property consists of 7 structures - six residential condominium buildings and one pool equipment building. All of the buildings are of ISO6 (reinforced masonry) construction. The exterior walls are stucco on masonry. The roof coverings on all residential buildings are tar & gravel.

In addition to the structure there are several site additions including 2 resort size swimming pools, 2 kiddie pools, 2 tennis courts, seawall, fencing, parking area light poles and an elevated wooden beach stairs.

<u>Building</u>	<u>Hazard/ Wind Value</u>	<u>Flood Value</u>
Building A	\$ 1,324,160	\$ 1,640,922
Building B	\$ 3,845,974	\$ 4,868,688
Building C	\$ 2,314,718	\$ 2,898,240
Building D	\$ 2,495,113	\$ 3,113,221
Building E	\$ 3,776,314	\$ 4,775,982
Building F	\$ 2,547,200	\$ 3,195,758
Pool Bldg	\$ 55,101	\$ 55,101
<u>Totals:</u>	<u>\$ 16,358,580</u>	<u>\$ 20,547,912</u>

Florida Replacement Cost Values: Over the last few years Florida has seen steady increases in the cost of construction (material and labor). This impacts new construction as well as and replacement values. Historically, the increase throughout Florida has averaged 3%-5% per year. These vary slightly with the geographic location. However, both construction materials as well as labor costs have increased greatly in 2021, 2022, 2023 and 2024. The average construction cost increase in Florida for 2021 was 14.2%, 9.7% in 2022, 9.4% in 2023 and 7.2% in 2024. Also, for structures located on barrier islands (with access only by bridge) the method of valuation has been modified. It now reflects the additional cost associated with transporting labor and materials to the location with longer and more limited access. This method more accurately estimates the correct replacement cost.

These insurance replacement valuation amounts are based on current market conditions for the geographic area where these structures are located. If an event of sufficient magnitude occurs in a large area and results in the destruction of these improvements, it is possible that debris removal and construction costs will spike upward at that time.

- Insurance Replacement Cost Valuation -

Site Improvements:

Swimming Pools (Resort) 2	\$ 334,688
Swimming Pools (Kiddie) 2	\$ 75,128
Tennis Courts 2	\$ 66,850
Fencing	\$ 7,816
Concrete Seawall	\$ 422,800
Concrete Retaining Walls (Dumpsters)	\$ 99,400
Elevated Wooden Beach Stairs	\$ 13,440
Light Poles	\$ 4,152
Entry Sign Monument	\$ 7,560
Flagpole	\$ 5,338
Pool Area Pavers	\$ 135,270

Florida Replacement Cost Values: Over the last few years Florida has seen steady increases in the cost of construction (material and labor). This impacts new construction as well as and replacement values. Historically, the increase throughout Florida has averaged 3%-5% per year. These vary slightly with the geographic location. However, both construction materials as well as labor costs have increased greatly in 2021, 2022, 2023 and 2024. The average construction cost increase in Florida for 2021 was 14.2%, 9.7% in 2022, 9.4% in 2023 and 7.2% in 2024. Also, for structures located on barrier islands (with access only by bridge) the method of valuation has been modified. It now reflects the additional cost associated with transporting labor and materials to the location with longer and more limited access. This method more accurately estimates the correct replacement cost.

These insurance replacement valuation amounts are based on current market conditions for the geographic area where these structures are located. If an event of sufficient magnitude occurs in a large area and results in the destruction of these improvements, it is possible that debris removal and construction costs will spike upward at that time.

VALUATION

Valuation Number:	ESTIMATE-0001542	Effective Date:	05/20/2025
Value Basis:	Reconstruction	Expiration Date:	05/20/2026
		Estimate Expiration Date:	08/18/2025
		Cost as of:	03/2025
		Valuation Modified Date:	05/21/2025

BUSINESS

Southeaster Condominium Association
4841 SAXON DR
NEW SMYRNA BEACH, FL 32169 USA

LOCATION 1 – Southeaster Condominium Association

Southeaster Condominium Association	Climatic Region:	3 – Warm
4841 SAXON DR	High Wind Region:	2 – Moderate Damage
NEW SMYRNA BEACH, FL 32169 USA	Seismic Zone:	1 – No Damage

BUILDING 1 – Building A**Section 1****SUPERSTRUCTURE**

Occupancy:	100% Condominium, w/o Interior Finishes	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	2
Gross Floor Area:	7,502 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees:	7% is included	Overhead and Profit:	20% is included
-----------------	----------------	----------------------	-----------------

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$1,310	
Foundations			\$71,461	
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$364,496	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$211,984	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$244,360	
Floor Finish				
Ceiling Finish		100% Drywall		
Partitions				
Length		1,071 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
Mechanicals			\$281,257	
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			
Fire Protection	0% Sprinkler System			
	0% Manual Fire Alarm System			
	0% Automatic Fire Alarm System			

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Plumbing		51 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger		
		0 Freight		
Built-ins			\$90,750	
SUBTOTAL RC			\$1,265,617	
ADDITIONS				
Building Items			\$58,543	
Total Additions			\$58,543	
TOTAL RC Section 1			\$1,324,160	

TOTAL RC BUILDING 1 Building A**\$1,324,160****BUILDING 2 – Building B****Section 1****SUPERSTRUCTURE**

Occupancy:	100% Condominium, w/o Interior Finishes	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	3
Gross Floor Area:	24,192 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees:	7% is included	Overhead and Profit:	20% is included
-----------------	----------------	----------------------	-----------------

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$2,817	



Valuation Detailed Report

Commercial Valuation
Hazard/Wind

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Foundations			\$128,131	
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$1,173,856	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$406,205	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$768,701	
Floor Finish				
Ceiling Finish		100% Drywall		
Partitions				
Length		3,456 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
Mechanicals			\$897,879	
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			
Fire Protection	0% Sprinkler System			
	0% Manual Fire Alarm System			
	0% Automatic Fire Alarm System			
Plumbing		162 Total Fixtures		

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Electrical		100% Average Quality		
Elevators		0 Passenger 0 Freight		
Built-ins			\$292,646	
SUBTOTAL RC			\$3,670,235	
ADDITIONS				
Building Items			\$175,739	
Total Additions			\$175,739	
TOTAL RC Section 1			\$3,845,974	

TOTAL RC BUILDING 2 Building B**\$3,845,974****BUILDING 3 – Building C****Section 1****SUPERSTRUCTURE**

Occupancy:	100% Condominium, w/o Interior Finishes	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	4
Gross Floor Area:	13,824 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees:	7% is included	Overhead and Profit:	20% is included
-----------------	----------------	----------------------	-----------------

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$1,207	
Foundations			\$67,277	



Valuation Detailed Report

Commercial Valuation
Hazard/Wind

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$844,119	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$198,102	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$451,842	
Floor Finish				
Ceiling Finish		100% Drywall		
Partitions				
Length		1,974 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
Mechanicals			\$514,658	
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			
Fire Protection	0% Sprinkler System			
	0% Manual Fire Alarm System			
	0% Automatic Fire Alarm System			
Plumbing		93 Total Fixtures		
Electrical		100% Average Quality		



Valuation Detailed Report

Commercial Valuation
Hazard/Wind

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Elevators		0 Passenger 0 Freight		
Built-ins			\$167,227	
SUBTOTAL RC			\$2,244,433	
ADDITIONS				
Building Items			\$70,284	
Total Additions			\$70,284	
TOTAL RC Section 1			\$2,314,718	

TOTAL RC BUILDING 3 Building C

\$2,314,718

BUILDING 4 – Building D

Section 1

SUPERSTRUCTURE

Occupancy:	100% Condominium, w/o Interior Finishes	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	4
Gross Floor Area:	14,688 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees:	7% is included	Overhead and Profit:	20% is included
-----------------	----------------	----------------------	-----------------

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$1,283	
Foundations			\$70,346	
Foundation Wall				



Valuation Detailed Report

Commercial Valuation
Hazard/Wind

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Interior Foundations				
Slab On Ground				
Exterior			\$885,805	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$208,278	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$479,020	
Floor Finish				
Ceiling Finish		100% Drywall		
Partitions				
Length		2,098 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
Mechanicals			\$543,820	
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			
Fire Protection	0% Sprinkler System			
	0% Manual Fire Alarm System			
	0% Automatic Fire Alarm System			
Plumbing		98 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger		
		0 Freight		

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Built-ins			\$177,678	
SUBTOTAL RC			\$2,366,231	
ADDITIONS				
Building Items			\$128,882	
Total Additions			\$128,882	
TOTAL RC Section 1			\$2,495,113	

TOTAL RC BUILDING 4 Building D	\$2,495,113
---------------------------------------	--------------------

BUILDING 5 – Building E**Section 1****SUPERSTRUCTURE**

Occupancy:	100% Condominium, w/o Interior Finishes	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	3
Gross Floor Area:	23,688 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees:	7% is included	Overhead and Profit:	20% is included
-----------------	----------------	----------------------	-----------------

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$2,758	
Foundations			\$126,029	
Foundation Wall				
Interior Foundations				
Slab On Ground				



Valuation Detailed Report

Commercial Valuation
Hazard/Wind

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Exterior			\$1,153,543	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$398,843	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$753,124	
Floor Finish				
Ceiling Finish		100% Drywall		
Partitions				
Length		3,384 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
Mechanicals			\$876,862	
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			
Fire Protection	0% Sprinkler System			
	0% Manual Fire Alarm System			
	0% Automatic Fire Alarm System			
Plumbing		158 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger		
		0 Freight		

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Built-ins			\$286,550	
SUBTOTAL RC			\$3,597,709	
ADDITIONS				
Building Items			\$178,605	
Total Additions			\$178,605	
TOTAL RC Section 1			\$3,776,314	

TOTAL RC BUILDING 5 Building E	\$3,776,314
---------------------------------------	--------------------

BUILDING 6 – Building F**Section 1****SUPERSTRUCTURE**

Occupancy:	100% Condominium, w/o Interior Finishes	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	3
Gross Floor Area:	15,377 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees:	7% is included	Overhead and Profit:	20% is included
-----------------	----------------	----------------------	-----------------

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$1,791	
Foundations			\$90,283	
Foundation Wall				
Interior Foundations				
Slab On Ground				



Valuation Detailed Report

Commercial Valuation
Hazard/Wind

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Exterior			\$810,757	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$275,362	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$495,308	
Floor Finish				
Ceiling Finish		100% Drywall		
Partitions				
Length		2,196 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
Mechanicals			\$570,820	
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			
Fire Protection	0% Sprinkler System			
	0% Manual Fire Alarm System			
	0% Automatic Fire Alarm System			
Plumbing		103 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger		
		0 Freight		



Valuation Detailed Report

Commercial Valuation
Hazard/Wind

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Built-ins			\$186,013	
SUBTOTAL RC			\$2,430,335	
ADDITIONS				
Building Items			\$116,865	
Total Additions			\$116,865	
TOTAL RC Section 1			\$2,547,200	

TOTAL RC BUILDING 6 Building F	\$2,547,200
---------------------------------------	--------------------

BUILDING 7 – Pool Equipment Building

Section 1

SUPERSTRUCTURE

Occupancy:	100% Utility Building	Story Height:	8 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	1
Gross Floor Area:	390 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees:	7% is included	Overhead and Profit:	20% is included
-----------------	----------------	----------------------	-----------------

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$130	
Foundations			\$7,076	
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$18,548	



Valuation Detailed Report

Commercial Valuation
Hazard/Wind

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Framing				
Exterior Wall		5% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$19,828	
Material	100% None			
Pitch				
Interior				
Floor Finish				
Ceiling Finish				
Partitions				
Length				
Structure	100% Concrete Block			
Finish	100% None			
Mechanicals			\$9,519	
Heating	100% None			
Cooling				
Fire Protection		0% Sprinkler System		
		0% Manual Fire Alarm System		
		0% Automatic Fire Alarm System		
Plumbing		1 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger		
		0 Freight		
Built-ins				
TOTAL RC Section 1			\$55,101	
TOTAL RC BUILDING 7 Pool Equipment Building			\$55,101	



Valuation Detailed Report

Commercial Valuation
Hazard/Wind

Policy Number: ESTIMATE-0001542

5/21/2025

	Reconstruction	Sq.Ft.	\$/Sq.Ft.
LOCATION SUBTOTAL (All Buildings)	\$16,358,580	99,661	\$164
LOCATION ADDITIONS			
Site Improvements	\$1,012,018		
Custom Items			
Monument Sign	\$7,560		
Light Poles	\$4,152		
Beach Stairs (Wood)	\$13,440		
Shuffleboard Courts (2)	\$6,725		
Pool Area Pavers	\$135,270		
Location Additions Value	\$1,179,165		
LOCATION TOTAL, Location 1	\$17,537,745	99,661	\$176
	Reconstruction	Sq.Ft.	\$/Sq.Ft.
VALUATION GRAND TOTAL	\$17,537,745	99,661	\$176



Valuation Detailed Report

Commercial Valuation
Hazard/Wind
EQUIPMENT REPORT

Policy Number: ESTIMATE-0001542

5/21/2025

VALUATION

Valuation Number:	ESTIMATE-0001542	Effective Date:	05/20/2025
Value Basis:	Reconstruction	Expiration Date:	05/20/2026
		Estimate Expiration Date:	08/18/2025
		Cost as of:	03/2025
		Valuation Modified Date:	05/21/2025

BUSINESS

Southeaster Condominium Association
4841 SAXON DR
NEW SMYRNA BEACH, FL 32169 USA

LOCATION 1 – Southeaster Condominium Association

Southeaster Condominium Association
4841 SAXON DR
NEW SMYRNA BEACH, FL 32169 USA

Equipment: Building items and site improvements

	Replacement	Depreciated
Building 1, Section 1		
Building Items		
Balconies		
(1) Balconies, Reinforced concrete frame	\$58,543	\$58,543
Building 2, Section 1		
Building Items		
Balconies		
(1) Balconies, Reinforced concrete frame	\$175,739	\$175,739
Building 3, Section 1		
Building Items		
Balconies		
(1) Balconies, Reinforced concrete frame	\$70,284	\$70,284
Building 4, Section 1		
Building Items		

Equipment: Building items and site improvements

	Replacement	Depreciated
Balconies		
(1) Balconies, Reinforced concrete frame	\$128,882	\$128,882
Building 5, Section 1		
Building Items		
Balconies		
(1) Balconies, Reinforced concrete frame	\$178,605	\$178,605
Building 6, Section 1		
Building Items		
Balconies		
(1) Balconies, Reinforced concrete frame	\$116,865	\$116,865
LOCATION 1 Additions		
Custom Items		
(1) Monument Sign	\$7,560	\$7,560
(1) Light Poles	\$4,152	\$4,152
(1) Beach Stairs (Wood)	\$13,440	\$13,440
(1) Shuffleboard Courts (2)	\$6,725	\$6,725
(1) Pool Area Pavers	\$135,270	\$135,270
Site Improvements		
Fences		
(1) Galvanized steel, 9 gauge wire	\$7,816	\$7,816
Flagpoles		
(1) Flagpoles, 30 Ft, Tapered aluminum	\$5,338	\$5,338
Retaining Walls		
(1) Concrete, 15 Ft, Concrete gravity wall	\$422,800	\$422,800
(1) Concrete, 8 Ft, Concrete gravity wall	\$99,400	\$99,400
Swimming Pools		
(2) Cast-in-place concrete or gunite sprayed-on concre, 2,000 SF Water Surface Area	\$334,688	\$334,688



Valuation Detailed Report

Commercial Valuation
Hazard/Wind
EQUIPMENT REPORT

Policy Number: ESTIMATE-0001542

5/21/2025

Equipment: Building items and site improvements		
	Replacement	Depreciated
(2) Cast-in-place concrete or gunite sprayed-on concre, 500 SF Water Surface Area	\$75,128	\$75,128
Tennis Courts		
(2) Tennis courts, Asphalt	\$66,850	\$66,850
LOCATION 1 - Southeaster Condominium Association TOTAL	\$1,908,083	\$1,908,083
TOTAL	\$1,908,083	\$1,908,083



Valuation Detailed Report

Commercial Valuation

Hazard/Wind

SUMMARY REPORT

Policy Number: ESTIMATE-0001542

5/21/2025

VALUATION

Valuation Number:	ESTIMATE-0001542	Effective Date:	05/20/2025
Value Basis:	Reconstruction	Expiration Date:	05/20/2026
		Estimate Expiration Date:	08/18/2025
		Cost as of:	03/2025
		Valuation Modified Date:	05/21/2025

BUSINESS

Southeaster Condominium Association

4841 SAXON DR

NEW SMYRNA BEACH, FL 32169 USA

LOCATION 1 – Southeaster Condominium Association

Southeaster Condominium Association

4841 SAXON DR

NEW SMYRNA BEACH, FL 32169 USA

BUILDING 1: SUPERSTRUCTURE

			Reconstruction	Sq.Ft.	\$/Sq.Ft.
Section 1	100%	Condominium, w/o Interior Finishes	\$1,265,617	7,502	\$169

Section Totals

			Reconstruction	Sq.Ft.	\$/Sq.Ft.
Section 1	100%	Condominium, w/o Interior Finishes	\$1,265,617	7,502	\$169

Total Additions: \$58,543

BUILDING TOTAL, Building 1

\$1,324,160 7,502 \$177

BUILDING INSURANCE SUMMARY

Total Insured Amount \$0

Percent of Insurance to Value 0%

100% Co-insurance Requirement \$1,324,160 \$1,324,160

-100% Variance (\$1,324,160)

BUILDING 2: SUPERSTRUCTURE

			Reconstruction	Sq.Ft.	\$/Sq.Ft.
Section 1	100%	Condominium, w/o Interior Finishes	\$3,670,235	24,192	\$152

Section Totals			Reconstruction	Sq.Ft.	\$/Sq.Ft.
Section 1	100%	Condominium, w/o Interior Finishes	\$3,670,235	24,192	\$152
Total Additions:			\$175,739		

BUILDING TOTAL, Building 2	\$3,845,974	24,192	\$159
-----------------------------------	--------------------	---------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount	\$0	
Percent of Insurance to Value	0%	
100% Co-insurance Requirement	\$3,845,974	\$3,845,974
-100% Variance	(\$3,845,974)	

BUILDING 3: SUPERSTRUCTURE			Reconstruction	Sq.Ft.	\$/Sq.Ft.
Section 1	100%	Condominium, w/o Interior Finishes	\$2,244,433	13,824	\$162

Section Totals			Reconstruction	Sq.Ft.	\$/Sq.Ft.
Section 1	100%	Condominium, w/o Interior Finishes	\$2,244,433	13,824	\$162
Total Additions:			\$70,284		

BUILDING TOTAL, Building 3	\$2,314,718	13,824	\$167
-----------------------------------	--------------------	---------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount	\$0	
Percent of Insurance to Value	0%	
100% Co-insurance Requirement	\$2,314,718	\$2,314,718
-100% Variance	(\$2,314,718)	

BUILDING 4: SUPERSTRUCTURE			Reconstruction	Sq.Ft.	\$/Sq.Ft.
Section 1	100%	Condominium, w/o Interior Finishes	\$2,366,231	14,688	\$161

Section Totals			Reconstruction	Sq.Ft.	\$/Sq.Ft.
Section 1	100%	Condominium, w/o Interior Finishes	\$2,366,231	14,688	\$161
Total Additions:			\$128,882		

BUILDING TOTAL, Building 4	\$2,495,113	14,688	\$170
-----------------------------------	--------------------	---------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount	\$0	
Percent of Insurance to Value	0%	
100% Co-insurance Requirement	\$2,495,113	\$2,495,113
-100% Variance	(\$2,495,113)	

BUILDING 5: SUPERSTRUCTURE	Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------------------	-----------------------	---------------	------------------

Section 1	100%	Condominium, w/o Interior Finishes	\$3,597,709	23,688	\$152
-----------	------	------------------------------------	-------------	--------	-------

Section Totals			Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------	--	--	-----------------------	---------------	------------------

Section 1	100%	Condominium, w/o Interior Finishes	\$3,597,709	23,688	\$152
-----------	------	------------------------------------	-------------	--------	-------

Total Additions:	\$178,605
------------------	-----------

BUILDING TOTAL, Building 5	\$3,776,314	23,688	\$159
-----------------------------------	--------------------	---------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount	\$0	
Percent of Insurance to Value	0%	
100% Co-insurance Requirement	\$3,776,314	\$3,776,314
-100% Variance	(\$3,776,314)	

BUILDING 6: SUPERSTRUCTURE	Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------------------	-----------------------	---------------	------------------

Section 1	100%	Condominium, w/o Interior Finishes	\$2,430,335	15,377	\$158
-----------	------	------------------------------------	-------------	--------	-------

Section Totals			Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------	--	--	-----------------------	---------------	------------------

Section 1	100%	Condominium, w/o Interior Finishes	\$2,430,335	15,377	\$158
-----------	------	------------------------------------	-------------	--------	-------

Total Additions:	\$116,865
------------------	-----------

BUILDING TOTAL, Building 6	\$2,547,200	15,377	\$166
-----------------------------------	--------------------	---------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount	\$0	
Percent of Insurance to Value	0%	
100% Co-insurance Requirement	\$2,547,200	\$2,547,200



Valuation Detailed Report

Commercial Valuation

Hazard/Wind

SUMMARY REPORT

Policy Number: ESTIMATE-0001542

5/21/2025

-100% Variance (\$2,547,200)

BUILDING 7: SUPERSTRUCTURE

Reconstruction

Sq.Ft.

\$/Sq.Ft.

Section 1 100% Utility Building

\$55,101

390

\$141

Section Totals

Reconstruction

Sq.Ft.

\$/Sq.Ft.

Section 1 100% Utility Building

\$55,101

390

\$141

BUILDING TOTAL, Building 7

\$55,101

390

\$141

BUILDING INSURANCE SUMMARY

Total Insured Amount

\$0

Percent of Insurance to Value

0%

100% Co-insurance Requirement

\$55,101

\$55,101

-100% Variance

(\$55,101)

Reconstruction

Sq.Ft.

\$/Sq.Ft.

LOCATION SUBTOTAL (All Buildings)

\$16,358,580

99,661

\$164

Total Location Additions

\$1,179,165

LOCATION TOTAL, Location 1

\$17,537,745

99,661

\$176

Reconstruction

Sq.Ft.

\$/Sq.Ft.

VALUATION GRAND TOTAL

\$17,537,745

99,661

\$176

End of Report

© 2025 CoreLogic, Inc. All rights reserved. Confidential. The use, distribution, or reproduction of this report, in whole or in part, for any purpose other than as permitted without the prior written consent of CoreLogic is strictly prohibited. No right or license is granted to use any patent, trade secret, trademark, copyright, or other technology know-how owned, controlled, or held by CoreLogic. The unauthorized disclosure of this report or any of the contents thereof without the express prior written consent of CoreLogic may cause CoreLogic irreparable injury, such that no remedy at law will afford it adequate protection against, or appropriate compensation for, such injury and CoreLogic shall be entitled to seek an injunction or other equitable relief, damages, or other relief as may be granted by a court of competent jurisdiction. The content and information in this report is provided "as is" without guarantee or warranty of any kind, express or implied, including without limitation, any guarantees or warranties of completeness, accuracy, applicability, merchantability, non-infringement of intellectual property rights, or fitness for a particular purpose including, but not limited to, any guarantees or warranties in connection with any of your and/or CoreLogic's inputs or any AI features or content of this report. CoreLogic is not responsible for your inputs and/or use of, nor any decisions based on or in reliance on, this report. CoreLogic does not guarantee, represent or warrant that this report is complete or free from error and does not assume, and expressly disclaims, any liability to any person or entity for any loss or damage caused or resulting in whole or in part by any reliance on this report including, but not limited to, any loss or damage caused or resulting in whole or in part by errors or omissions in this report and/or any AI features or content thereof and/or errors or omissions in your or CoreLogic's inputs. CoreLogic costs include labor and material, normal profit, and overhead as of the date of the report, represent general estimates which are not to be considered a detailed quantity survey, and include generalities and assumptions that are common to the types of structures represented in the software. The commercial contents values included in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured. CoreLogic®, Commercial Valuation®, and Commercial ExpressLync® are the registered trademarks of CoreLogic, Inc. or its affiliates or subsidiaries.

VALUATION

Valuation Number:	ESTIMATE-0001542	Effective Date:	05/20/2025
Value Basis:	Reconstruction	Expiration Date:	05/20/2026
		Estimate Expiration Date:	08/18/2025
		Cost as of:	03/2025
		Valuation Modified Date:	05/21/2025

BUSINESS

Southeaster Condominium Association
4841 SAXON DR
NEW SMYRNA BEACH, FL 32169 USA

LOCATION 1 – Southeaster Condominium Association

Southeaster Condominium Association	Climatic Region:	3 – Warm
4841 SAXON DR	High Wind Region:	2 – Moderate Damage
NEW SMYRNA BEACH, FL 32169 USA	Seismic Zone:	1 – No Damage

BUILDING 1 – Building A**Section 1****SUPERSTRUCTURE**

Occupancy:	100% Condominium	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	2
Gross Floor Area:	7,502 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees:	7% is included	Overhead and Profit:	20% is included
-----------------	----------------	----------------------	-----------------

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
------------------	---------------	-----------------	----------------	-----------



Valuation Detailed Report

Commercial Valuation
Flood

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$1,277	
Foundations			\$69,613	
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$355,069	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$206,501	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$317,404	
Floor Finish		80% Carpet		
		10% Tile, Ceramic		
		10% Vinyl Sheet		
Ceiling Finish		100% Drywall		
		100% Paint		
Partitions				
Length		1,071 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
		100% Paint		
Mechanicals			\$530,214	
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			



Valuation Detailed Report

Commercial Valuation
Flood

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Fire Protection	0% Sprinkler System 0% Manual Fire Alarm System 0% Automatic Fire Alarm System			
Plumbing		51 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger 0 Freight		
Built-ins			\$102,302	
SUBTOTAL RC			\$1,582,380	
ADDITIONS				
Building Items			\$58,543	
Total Additions			\$58,543	
TOTAL RC Section 1			\$1,640,922	

TOTAL RC BUILDING 1 Building A

\$1,640,922

BUILDING 2 – Building B

Section 1

SUPERSTRUCTURE

Occupancy:	100% Condominium	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	3
Gross Floor Area:	24,192 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees: 7% is included Overhead and Profit: 20% is included

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$2,744	
Foundations			\$124,818	
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$1,143,497	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$395,700	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$1,002,045	
Floor Finish		80% Carpet		
		10% Tile, Ceramic		
		10% Vinyl Sheet		
Ceiling Finish		100% Drywall		
		100% Paint		
Partitions				
Length		3,456 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
		100% Paint		



Valuation Detailed Report

Commercial Valuation
Flood

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Mechanicals			\$1,694,248	
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			
Fire Protection	0% Sprinkler System 0% Manual Fire Alarm System 0% Automatic Fire Alarm System			
Plumbing		162 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger 0 Freight		
Built-ins			\$329,897	
SUBTOTAL RC			\$4,692,949	
ADDITIONS				
Building Items			\$175,739	
Total Additions			\$175,739	
TOTAL RC Section 1			\$4,868,688	

TOTAL RC BUILDING 2 Building B

\$4,868,688

BUILDING 3 – Building C

Section 1

SUPERSTRUCTURE

Occupancy:	100% Condominium	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	4
Gross Floor Area:	13,824 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		



Valuation Detailed Report

Commercial Valuation
Flood

Policy Number: ESTIMATE-0001542

5/21/2025

Adjustments			
Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good
Fees			
Architect Fees:	7% is included	Overhead and Profit:	20% is included

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$1,176	
Foundations			\$65,537	
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$822,289	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$192,979	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$586,612	
Floor Finish		80% Carpet		
		10% Tile, Ceramic		
		10% Vinyl Sheet		
Ceiling Finish		100% Drywall		
		100% Paint		
Partitions				
Length		1,974 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
		100% Paint		
Mechanicals			\$970,850	
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Fire Protection	0% Sprinkler System 0% Manual Fire Alarm System 0% Automatic Fire Alarm System			
Plumbing		93 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger 0 Freight		
Built-ins			\$188,513	
SUBTOTAL RC			\$2,827,955	
ADDITIONS				
Building Items			\$70,284	
Total Additions			\$70,284	
TOTAL RC Section 1			\$2,898,240	

TOTAL RC BUILDING 3 Building C**\$2,898,240****BUILDING 4 - Building D****Section 1****SUPERSTRUCTURE**

Occupancy:	100% Condominium	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	4
Gross Floor Area:	14,688 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 - 2.0 - Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees: 7% is included Overhead and Profit: 20% is included

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
------------------	---------------	-----------------	----------------	-----------

SUPERSTRUCTURE

Site Preparation			\$1,250	
Foundations			\$68,527	
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$862,897	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$202,891	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$622,085	
Floor Finish		80% Carpet		
		10% Tile, Ceramic		
		10% Vinyl Sheet		
Ceiling Finish		100% Drywall		
		100% Paint		
Partitions				
Length		2,098 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
		100% Paint		
Mechanicals			\$1,026,394	

Policy Number: ESTIMATE-0001542

5/21/2025

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			
Fire Protection	0% Sprinkler System			
	0% Manual Fire Alarm System			
	0% Automatic Fire Alarm System			
Plumbing		98 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger		
		0 Freight		
Built-ins			\$200,295	
SUBTOTAL RC			\$2,984,339	
ADDITIONS				
Building Items			\$128,882	
Total Additions			\$128,882	
TOTAL RC Section 1			\$3,113,221	

TOTAL RC BUILDING 4 Building D**\$3,113,221****BUILDING 5 – Building E****Section 1****SUPERSTRUCTURE**

Occupancy:	100% Condominium	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	3
Gross Floor Area:	23,688 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		



Valuation Detailed Report
Commercial Valuation
Flood

Policy Number: ESTIMATE-0001542

5/21/2025

Adjustments			
Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good
Fees			
Architect Fees:	7% is included	Overhead and Profit:	20% is included

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$2,687	
Foundations			\$122,769	
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$1,123,710	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$388,528	
Material	100% Built-Up, Smooth			
Pitch	100% Flat			
Interior			\$981,656	
Floor Finish		80% Carpet		
		10% Tile, Ceramic		
		10% Vinyl Sheet		
Ceiling Finish		100% Drywall		
		100% Paint		
Partitions				
Length		3,384 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
		100% Paint		
Mechanicals			\$1,655,002	
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Fire Protection	0% Sprinkler System 0% Manual Fire Alarm System 0% Automatic Fire Alarm System			
Plumbing		158 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger 0 Freight		
Built-ins			\$323,024	
SUBTOTAL RC			\$4,597,377	
ADDITIONS				
Building Items			\$178,605	
Total Additions			\$178,605	
TOTAL RC Section 1			\$4,775,982	

TOTAL RC BUILDING 5 Building E**\$4,775,982****BUILDING 6 – Building F****Section 1****SUPERSTRUCTURE**

Occupancy:	100% Condominium	Story Height:	9 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	3
Gross Floor Area:	15,377 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		

Adjustments

Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good

Fees

Architect Fees: 7% is included Overhead and Profit: 20% is included

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
------------------	---------------	-----------------	----------------	-----------

SUPERSTRUCTURE

Site Preparation \$1,744

Foundations \$87,948

Foundation Wall

Interior Foundations

Slab On Ground

Exterior \$789,790

Framing

Exterior Wall 25% Wall Openings

Exterior Wall 100% Stucco on
Masonry

Structural Floor

Roof \$268,241

Material 100% Built-Up, Smooth

Pitch 100% Flat

Interior \$644,392

Floor Finish 80% Carpet

10% Tile, Ceramic

10% Vinyl Sheet

Ceiling Finish 100% Drywall

100% Paint

Partitions

Length 2,196 ft.

Structure 100% Studs, Girts, etc.

Finish 100% Drywall

100% Paint

Mechanicals \$1,077,087

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
Heating		100% Forced Warm Air		
Cooling	100% Forced Cool Air			
Fire Protection	0% Sprinkler System 0% Manual Fire Alarm System 0% Automatic Fire Alarm System			
Plumbing		103 Total Fixtures		
Electrical		100% Average Quality		
Elevators		0 Passenger 0 Freight		
Built-ins			\$209,690	
SUBTOTAL RC			\$3,078,893	
ADDITIONS				
Building Items			\$116,865	
Total Additions			\$116,865	
TOTAL RC Section 1			\$3,195,758	

TOTAL RC BUILDING 6 Building F	\$3,195,758
---------------------------------------	--------------------

BUILDING 7 – Pool Equipment Building**Section 1****SUPERSTRUCTURE**

Occupancy:	100% Utility Building	Story Height:	8 ft.
Construction Type:	100% Reinforced Concrete Frame (ISO 6)	Number of Stories:	1
Gross Floor Area:	390 sq.ft.	Irregular Adjustment:	None
Construction Quality:	2.0 – 2.0 – Average		
Year Built:	1968		



Valuation Detailed Report

Commercial Valuation
Flood

Policy Number: ESTIMATE-0001542

5/21/2025

Adjustments			
Hillside Construction:	Degree of Slope: Flat	Site Accessibility:	Good
	Site Position: Unknown	Soil Condition:	Good
Fees			
Architect Fees:	7% is included	Overhead and Profit:	20% is included

SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation			\$130	
Foundations			\$7,076	
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$18,548	
Framing				
Exterior Wall		5% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$19,828	
Material	100% None			
Pitch				
Interior				
Floor Finish				
Ceiling Finish				
Partitions				
Length				
Structure	100% Concrete Block			
Finish	100% None			
Mechanicals			\$9,519	
Heating	100% None			
Cooling				
Fire Protection		0% Sprinkler System		
		0% Manual Fire Alarm System		
		0% Automatic Fire Alarm System		
Plumbing		1 Total Fixtures		



Valuation Detailed Report

Commercial Valuation
Flood

Policy Number: ESTIMATE-0001542

5/21/2025

	SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
	Electrical		100% Average Quality		
	Elevators		0 Passenger 0 Freight		
	Built-ins				
	TOTAL RC Section 1			\$55,101	
	TOTAL RC BUILDING 7 Pool Equipment Building			\$55,101	
			Reconstruction	Sq.Ft.	\$/Sq.Ft.
LOCATION SUBTOTAL (All Buildings)			\$20,547,912	99,661	\$206
LOCATION ADDITIONS					
	Site Improvements		\$1,012,018		
	Custom Items				
	Monument Sign		\$7,560		
	Light Poles		\$4,152		
	Beach Stairs (Wood)		\$13,440		
	Shuffleboard Courts (2)		\$6,725		
	Pool Area Pavers		\$135,270		
Location Additions Value			\$1,179,165		
LOCATION TOTAL, Location 1			\$21,727,077	99,661	\$218
			Reconstruction	Sq.Ft.	\$/Sq.Ft.
VALUATION GRAND TOTAL			\$21,727,077	99,661	\$218



Valuation Detailed Report

Commercial Valuation

Flood

EQUIPMENT REPORT

Policy Number: ESTIMATE-0001542

5/21/2025

VALUATION

Valuation Number:	ESTIMATE-0001542	Effective Date:	05/20/2025
Value Basis:	Reconstruction	Expiration Date:	05/20/2026
		Estimate Expiration Date:	08/18/2025
		Cost as of:	03/2025
		Valuation Modified Date:	05/21/2025

BUSINESS

Southeaster Condominium Association
4841 SAXON DR
NEW SMYRNA BEACH, FL 32169 USA

LOCATION 1 – Southeaster Condominium Association

Southeaster Condominium Association
4841 SAXON DR
NEW SMYRNA BEACH, FL 32169 USA

Equipment: Building items and site improvements

	Replacement	Depreciated
Building 1, Section 1		
Building Items		
Balconies		
(1) Balconies, Reinforced concrete frame	\$58,543	\$58,543
Building 2, Section 1		
Building Items		
Balconies		
(1) Balconies, Reinforced concrete frame	\$175,739	\$175,739
Building 3, Section 1		
Building Items		
Balconies		
(1) Balconies, Reinforced concrete frame	\$70,284	\$70,284
Building 4, Section 1		
Building Items		

Equipment: Building items and site improvements

	Replacement	Depreciated
Balconies		
(1) Balconies, Reinforced concrete frame	\$128,882	\$128,882
Building 5, Section 1		
Building Items		
Balconies		
(1) Balconies, Reinforced concrete frame	\$178,605	\$178,605
Building 6, Section 1		
Building Items		
Balconies		
(1) Balconies, Reinforced concrete frame	\$116,865	\$116,865
LOCATION 1 Additions		
Custom Items		
(1) Monument Sign	\$7,560	\$7,560
(1) Light Poles	\$4,152	\$4,152
(1) Beach Stairs (Wood)	\$13,440	\$13,440
(1) Shuffleboard Courts (2)	\$6,725	\$6,725
(1) Pool Area Pavers	\$135,270	\$135,270
Site Improvements		
Fences		
(1) Galvanized steel, 9 gauge wire	\$7,816	\$7,816
Flagpoles		
(1) Flagpoles, 30 Ft, Tapered aluminum	\$5,338	\$5,338
Retaining Walls		
(1) Concrete, 15 Ft, Concrete gravity wall	\$422,800	\$422,800
(1) Concrete, 8 Ft, Concrete gravity wall	\$99,400	\$99,400
Swimming Pools		
(2) Cast-in-place concrete or gunite sprayed-on concre, 2,000 SF Water Surface Area	\$334,688	\$334,688



Valuation Detailed Report

Commercial Valuation
Flood
EQUIPMENT REPORT

Policy Number: ESTIMATE-0001542

5/21/2025

Equipment: Building items and site improvements		
	Replacement	Depreciated
(2) Cast-in-place concrete or gunite sprayed-on concre, 500 SF Water Surface Area	\$75,128	\$75,128
Tennis Courts		
(2) Tennis courts, Asphalt	\$66,850	\$66,850
LOCATION 1 - Southeaster Condominium Association TOTAL	\$1,908,083	\$1,908,083
TOTAL	\$1,908,083	\$1,908,083



Valuation Detailed Report

Commercial Valuation

Flood

SUMMARY REPORT

Policy Number: ESTIMATE-0001542

5/21/2025

VALUATION

Valuation Number:	ESTIMATE-0001542	Effective Date:	05/20/2025
Value Basis:	Reconstruction	Expiration Date:	05/20/2026
		Estimate Expiration Date:	08/18/2025
		Cost as of:	03/2025
		Valuation Modified Date:	05/21/2025

BUSINESS

Southeaster Condominium Association

4841 SAXON DR

NEW SMYRNA BEACH, FL 32169 USA

LOCATION 1 – Southeaster Condominium Association

Southeaster Condominium Association

4841 SAXON DR

NEW SMYRNA BEACH, FL 32169 USA

BUILDING 1: SUPERSTRUCTURE

Section 1	100%	Condominium	\$1,582,380	7,502	\$211
-----------	------	-------------	-------------	-------	-------

Section Totals

Section 1	100%	Condominium	\$1,582,380	7,502	\$211
-----------	------	-------------	-------------	-------	-------

Total Additions:	\$58,543
------------------	----------

BUILDING TOTAL, Building 1

\$1,640,922	7,502	\$219
-------------	-------	-------

BUILDING INSURANCE SUMMARY

Total Insured Amount	\$0
----------------------	-----

Percent of Insurance to Value	0%
-------------------------------	----

100% Co-insurance Requirement	\$1,640,922	\$1,640,922
-------------------------------	-------------	-------------

-100% Variance	(\$1,640,922)
----------------	---------------

BUILDING 2: SUPERSTRUCTURE

Section 1	100%	Condominium	\$4,692,949	24,192	\$194
-----------	------	-------------	-------------	--------	-------

Section Totals

Section 1	100%	Condominium	\$4,692,949	24,192	\$194
-----------	------	-------------	-------------	--------	-------

Total Additions: \$175,739

BUILDING TOTAL, Building 2	\$4,868,688	24,192	\$201
-----------------------------------	--------------------	---------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount \$0

Percent of Insurance to Value 0%

100% Co-insurance Requirement \$4,868,688 \$4,868,688

-100% Variance (\$4,868,688)

BUILDING 3: SUPERSTRUCTURE	Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------------------	-----------------------	---------------	------------------

Section 1 100% Condominium \$2,827,955 13,824 \$205

Section Totals	Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------	-----------------------	---------------	------------------

Section 1 100% Condominium \$2,827,955 13,824 \$205

Total Additions: \$70,284

BUILDING TOTAL, Building 3	\$2,898,240	13,824	\$210
-----------------------------------	--------------------	---------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount \$0

Percent of Insurance to Value 0%

100% Co-insurance Requirement \$2,898,240 \$2,898,240

-100% Variance (\$2,898,240)

BUILDING 4: SUPERSTRUCTURE	Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------------------	-----------------------	---------------	------------------

Section 1 100% Condominium \$2,984,339 14,688 \$203

Section Totals	Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------	-----------------------	---------------	------------------

Section 1 100% Condominium \$2,984,339 14,688 \$203

Total Additions: \$128,882

BUILDING TOTAL, Building 4	\$3,113,221	14,688	\$212
-----------------------------------	--------------------	---------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount \$0

Percent of Insurance to Value 0%

100% Co-insurance Requirement \$3,113,221 \$3,113,221

-100% Variance (\$3,113,221)

BUILDING 5: SUPERSTRUCTURE	Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------------------	-----------------------	---------------	------------------

Section 1	100%	Condominium	\$4,597,377	23,688	\$194
-----------	------	-------------	-------------	--------	-------

Section Totals			Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------	--	--	-----------------------	---------------	------------------

Section 1	100%	Condominium	\$4,597,377	23,688	\$194
-----------	------	-------------	-------------	--------	-------

Total Additions:			\$178,605		
------------------	--	--	-----------	--	--

BUILDING TOTAL, Building 5			\$4,775,982	23,688	\$202
-----------------------------------	--	--	--------------------	---------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount		\$0
----------------------	--	-----

Percent of Insurance to Value		0%
-------------------------------	--	----

100% Co-insurance Requirement	\$4,775,982	\$4,775,982
-------------------------------	-------------	-------------

-100% Variance	(\$4,775,982)	
----------------	---------------	--

BUILDING 6: SUPERSTRUCTURE			Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------------------	--	--	-----------------------	---------------	------------------

Section 1	100%	Condominium	\$3,078,893	15,377	\$200
-----------	------	-------------	-------------	--------	-------

Section Totals			Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------	--	--	-----------------------	---------------	------------------

Section 1	100%	Condominium	\$3,078,893	15,377	\$200
-----------	------	-------------	-------------	--------	-------

Total Additions:			\$116,865		
------------------	--	--	-----------	--	--

BUILDING TOTAL, Building 6			\$3,195,758	15,377	\$208
-----------------------------------	--	--	--------------------	---------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount		\$0
----------------------	--	-----

Percent of Insurance to Value		0%
-------------------------------	--	----

100% Co-insurance Requirement	\$3,195,758	\$3,195,758
-------------------------------	-------------	-------------

-100% Variance	(\$3,195,758)	
----------------	---------------	--

BUILDING 7: SUPERSTRUCTURE			Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------------------	--	--	-----------------------	---------------	------------------

Section 1	100%	Utility Building	\$55,101	390	\$141
-----------	------	------------------	----------	-----	-------

Section Totals			Reconstruction	Sq.Ft.	\$/Sq.Ft.
-----------------------	--	--	-----------------------	---------------	------------------

Section 1	100%	Utility Building	\$55,101	390	\$141
-----------	------	------------------	----------	-----	-------

BUILDING TOTAL, Building 7			\$55,101	390	\$141
-----------------------------------	--	--	-----------------	------------	--------------

BUILDING INSURANCE SUMMARY

Total Insured Amount		\$0
----------------------	--	-----

Percent of Insurance to Value		0%
-------------------------------	--	----

100% Co-insurance Requirement	\$55,101	\$55,101
-------------------------------	----------	----------



Valuation Detailed Report

Commercial Valuation

Flood

SUMMARY REPORT

Policy Number: ESTIMATE-0001542


5/21/2025

-100% Variance	(\$55,101)		
	Reconstruction	Sq.Ft.	\$/Sq.Ft.
LOCATION SUBTOTAL (All Buildings)	\$20,547,912	99,661	\$206
Total Location Additions	\$1,179,165		
LOCATION TOTAL, Location 1	\$21,727,077	99,661	\$218
	Reconstruction	Sq.Ft.	\$/Sq.Ft.
VALUATION GRAND TOTAL	\$21,727,077	99,661	\$218

End of Report


© 2025 CoreLogic, Inc. All rights reserved. Confidential. The use, distribution, or reproduction of this report, in whole or in part, for any purpose other than as permitted without the prior written consent of CoreLogic is strictly prohibited. No right or license is granted to use any patent, trade secret, trademark, copyright, or other technology know-how owned, controlled, or held by CoreLogic. The unauthorized disclosure of this report or any of the contents thereof without the express prior written consent of CoreLogic may cause CoreLogic irreparable injury, such that no remedy at law will afford it adequate protection against, or appropriate compensation for, such injury and CoreLogic shall be entitled to seek an injunction or other equitable relief, damages, or other relief as may be granted by a court of competent jurisdiction. The content and information in this report is provided "as is" without guarantee or warranty of any kind, express or implied, including without limitation, any guarantees or warranties of completeness, accuracy, applicability, merchantability, non-infringement of intellectual property rights, or fitness for a particular purpose including, but not limited to, any guarantees or warranties in connection with any of your and/or CoreLogic's inputs or any AI features or content of this report. CoreLogic is not responsible for your inputs and/or use of, nor any decisions based on or in reliance on, this report. CoreLogic does not guarantee, represent or warrant that this report is complete or free from error and does not assume, and expressly disclaims, any liability to any person or entity for any loss or damage caused or resulting in whole or in part by any reliance on this report including, but not limited to, any loss or damage caused or resulting in whole or in part by errors or omissions in this report and/or any AI features or content thereof and/or errors or omissions in your or CoreLogic's inputs. CoreLogic costs include labor and material, normal profit, and overhead as of the date of the report, represent general estimates which are not to be considered a detailed quantity survey, and include generalities and assumptions that are common to the types of structures represented in the software. The commercial contents values included in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured. CoreLogic®, Commercial Valuation®, and Commercial ExpressLync® are the registered trademarks of CoreLogic, Inc. or its affiliates or subsidiaries.

Building A









Building B








Building C




Building D



Building E



Building F



Pool Equipment Building



Site Additions



ISO Types 1-6: Construction Code Descriptions

ISO 1 – Frame (combustible walls and/or roof)

Class 1B

Buildings where the exterior walls are wood or other combustible materials, including construction where the combustible materials are combined with other materials such as brick veneer, stone veneer, wood iron-clad and stucco on wood.

Wood frame walls, floors, and roof deck

Brick Veneer, wood/hardiplank siding, stucco cladding

Wood frame roof with wood decking and typical roof covers below:

- *Shingles
- *Clay/concrete tiles
- *BUR (built up roof with gravel or modified bitumen)
- *Single-ply membrane
- *Less Likely metal sheathing covering
- *May be gable, hip, flat or combination of geometries

Roof anchorage

- *Toe nailed
- *Clips
- *Single Wraps
- *Double Wraps

Examples: Primarily Habitational, max 3-4 stories

ISO 2 – Joisted Masonry (JM) (noncombustible masonry walls with wood frame roof)

Class 2B

Buildings where the exterior walls are wood or other combustible materials, including construction where the combustible materials are combined with other materials such as brick veneer, stone veneer, wood iron-clad and stucco on wood.

Concrete block, masonry, or reinforced masonry load bearing exterior walls

*if reported as CB walls only, verify if wood frame (ISO 2) or steel/noncombustible frame roof (ISO 4)

*verify if wood frame walls (Frame ISO 1) or wood framing in roof only (JM ISO 2)

Stucco, brick veneer, painted CB, or EIFS exterior cladding

Floors in multi-story buildings are wood framed/wood deck or can be concrete on wood or steel deck.

Wood frame roof with wood decking and typical roof covers below:

- *Shingles
- *Clay/concrete tiles
- *BUR (built up roof with gravel or modified bitumen)
- *Single-ply membrane
- *Less Likely metal sheathing covering
- *May be gable, hip, flat or combination of geometries

Roof anchorage

- *Toe nailed
- *Clips
- *Single Wraps
- *Double Wraps

Examples: Primarily Habitational, small office/retail, max 3-4 stories

If “tunnel form” construction meaning there is a concrete deck above the top floor ceiling with wood frame roof over the top concrete deck, this will react to wind forces much the same way as typical JM construction. It is slightly better from a fire rating standpoint and from a wind standpoint in terms of potential damage if the wood frame is damaged. Please provide comments in the construction details of SOV for this type of construction.

A subset of JM Construction is Heavy Timber Joisted Masonry JM Class II, also known as ISO 7 (Class 7AB). This is Joisted Masonry constructed buildings where the following additional conditions exist: Where the entire roof has a minimum thickness of 2 inches with Roof Supported by timber and having a minimum dimension of 6 inches, or where the entire roof assembly is documented to have a UL wind uplift classification of 90 or equivalent.

ISO Types 1-6: Construction Code Descriptions

ISO 3 - Non Combustible (NC)

Class 3B / NC-I (non-combustible)

Buildings where the exterior walls and the floors and roof are constructed of and supported by metal, asbestos, gypsum or other non-combustible materials.

Minimal combustible materials in the building construction

Typical steel frame walls with masonry in-fill, brick veneer, metal sheathing, EIFS. Steel framing is load bearing portion of the building frame. AMBS (all metal building system) pre-engineered construction is common. Light steel frame ISO 3 smaller geometry with no interior building support columns. Heavier ISO 3 larger geometries with internal support columns and heavier roof framing. If multi-story, floors are commonly concrete on steel frame on steel deck.

Roof deck and roof cover systems:

*Steel deck

- BUR (built up roof with gravel or modified bitumen)
- Single-ply membrane
- Lesser extent foam/spray applied roof which is typically applied over an existing roof cover – this is not considered a roof cover replacement.
- Usually flat/low sloped

*Metal

- Lap seam metal panel (exposed fasteners)
- Standing seam metal panel (concealed fasteners)
- May or may not be coated/sealed
- May be gable, hip, flat or combination of geometries

Roof anchorage:

*Light steel frame ISO 3 may still incorporate clips, single wraps, or double wraps

*Because of heavier construction with no wood framing in roof, roof to wall anchorage is typically an engineered bolted and/or **structural** roof connection. Toe nailing, Clips, single wraps, double wraps do not apply.

Examples: warehouses, manufacturing facilities

A subset of NC Construction is Superior Non-Combustible Construction NC-II, also known as ISO 8 (Class 8AB). This shall apply to Non-combustible constructed buildings where the following additional conditions exist: Where the entire roof is constructed of 2 inches of masonry on steel supports; or, where the entire roof is constructed of 22 gauge metal (or heavier) on steel supports; or, where the entire roof assembly is documented to have a wind uplift classification of 90 or equivalent.

ISO 4 - Masonry Non Combustible (MNC)

Class 4AB / MNC-I

Buildings where the exterior walls are constructed of masonry materials as described in code 2 above, with the floors and roof of metal or other non-combustible materials.

Concrete block, reinforced masonry, tilt-up concrete load bearing walls – may be combined with some heavy steel framing. Floors commonly concrete on steel deck for multi-story buildings. Roof construction is typically heavy steel frames.

Roof deck and roof cover systems:

*Steel deck with insulation boards (commonly called insulated steel deck roofing system)

- BUR (built up roof with gravel or modified bitumen)
- Single ply membrane
- Lesser extent foam/spray applied roof which is typically applied over an existing roof cover – this is not considered a roof cover replacement.
- Flat/low sloped

*Lightweight insulating concrete or gypsum board on steel deck

- BUR (built up roof with gravel or modified bitumen)
- Single ply membrane
- Lesser extent foam/spray applied roof which is typically applied over an existing roof cover – this is not considered a roof cover replacement.

ISO Types 1-6: Construction Code Descriptions

- Flat/slow slope
- Sometimes possibly heavier concrete on steel deck or precast concrete panels for roof frame may still be considered ISO 4 if exposed steel is not fire proofed to obtain fire ratings needed to be ISO 5.

- *Steel frame with metal sheathing roof cover
 - Lap seam metal panel (exposed fasteners)
 - Standing seam metal panel (concealed fasteners)
 - May or may not be coated/sealed
 - May be gable, hip, flat or combination of geometries

Roof anchorage

- *Because of heavier construction with no wood framing in roof, roof to wall anchorage is typically an engineered bolted and/or **structural** roof connection. Toe nailing, Clips, single wraps, double wraps do not apply.

Walls have minimum 1 hour fire rating

Examples: shopping centers, strip centers, office buildings, warehouses, schools

A subset of MNC Construction is Superior Masonry Non-Combustible Construction MNC-II, also known as ISO 9 (Class 9A). This shall apply to Masonry Non-combustible constructed buildings where the following additional conditions exist: Where the entire roof is constructed of 2 inches of masonry on steel supports; or, where the entire roof is constructed of 22 gauge metal (or heavier) on steel supports; or, where the entire roof assembly is documented to have wind uplift classification of 90 or equivalent.

ISO 5 - Modified or Semi Fire Resistive (MFR or SFR)

Class 5A

Overall construction of fire resistive materials with fire rating less than 2 hours but greater than 1 hour. Exterior walls, floors and roof deck typically of masonry materials not less than 4 in thick but less thick than required for the 2 hour minimum rating for fire resistive construction.

Protected steel and/or concrete or heavy masonry walls and floors.

Semi wind resistive

Roof deck and roof cover systems

- *Heavy steel frame with concrete poured on steel deck
 - BUR (built up roof with gravel or modified bitumen)
 - Single ply membrane
 - Lesser extent foam/spray applied roof which is typically applied over an existing roof cover – this is not considered a roof cover replacement.
 - Flat/low sloped
 - Exposed steel must be fireproofed to achieve required fire rating
- *Precast concrete (PC) panels
 - BUR (built up roof with gravel or modified bitumen)
 - Single ply membrane
 - Lesser extent foam/spray applied roof which is typically applied over an existing roof cover – this is not considered a roof cover replacement.
 - Flat/low sloped
- *Steel deck with insulation boards, gypsum, lightweight insulating concrete
 - BUR (built up roof with gravel or modified bitumen)
 - Single ply membrane
 - Lesser extent foam/spray applied roof which is typically applied over an existing roof cover – this is not considered a roof cover replacement.
 - Flat/low sloped
 - Exposed steel must be fire proofed to achieve required fire rating.

Roof anchorage

- *Because of heavier construction with no wood framing in roof, roof to wall anchorage is typically an engineered bolted and/or **structural** roof connection. Toe nailing, Clips, single wraps, double wraps do not apply.

Examples: high and mid-rise office buildings and condos

ISO Types 1-6: Construction Code Descriptions

ISO 6 - Fire Resistive (FR)

Class 6A

Fire rating not less than 2 hours for walls, floors, and roofs. This typically requires walls of masonry materials minimum of 4 in thick, hollow masonry minimum 8 in thick, floors and roofs minimum of 4 in thick reinforced concrete, and any structural steel load bearing components with minimum of 2 hour fire rating,

Reinforced Concrete Construction building frame and floors and/or very well protected steel and concrete Floors are minimum 4" cast in place concrete, precast concrete or concrete on protected steel

Wind resistive

Precast construction - brought in from elsewhere / Cast in Place is poured on site

Roof deck and roof cover systems

- *Cast in place reinforced concrete or precast concrete

- BUR (built up roof with gravel or modified bitumen)

- Single ply membrane

- Lesser extent foam/spray applied roof which is typically applied over an existing roof cover – this is not considered a roof cover replacement

- Flat/low sloped

- In some cases, structural concrete poured on steel deck, but exposed steel must be fireproofed to achieve required minimum 2 hour fire rating

- If exposed concrete, such as on parking deck, leave roof cover as Unknown on SOV. This is typically an exposed or sealed concrete roof deck and the ISO 5 or 6 construction and occupancy will account for the roof deck/cover type. Can provide construction comment on SOV.

Roof anchorage

- *Because of heavier construction with no wood framing in roof, roof to wall anchorage is typically an engineered bolted and/or **structural** roof connection. Toe nailing, Clips, single wraps, double wraps do not apply.

Examples: high-rise office buildings and condos, parking garages

Florida Statutes 718.111 (11) Insurance

11) INSURANCE.—In order to protect the safety, health, and welfare of the people of the State of Florida and to ensure consistency in the provision of insurance coverage to condominiums and their unit owners, this subsection applies to every residential condominium in the state, regardless of the date of its declaration of condominium. It is the intent of the Legislature to encourage lower or stable insurance premiums for associations described in this subsection.

(a) Adequate property insurance, regardless of any requirement in the declaration of condominium for coverage by the association for full insurable value, **replacement cost, or similar coverage, must be based on the replacement cost of the property to be insured as determined by an independent insurance appraisal or update of a prior appraisal. The replacement cost must be determined at least once every 36 months.**

1. An association or group of associations may provide adequate property insurance through a self-insurance fund that complies with the requirements of ss. [624.460-624.488](#).

2. The association may also provide adequate property insurance coverage for a group of at least three communities created and operating under this chapter, chapter 719, chapter 720, or chapter 721 by obtaining and maintaining for such communities insurance coverage sufficient to cover an amount equal to the probable maximum loss for the communities for a 250-year windstorm event. Such probable maximum loss must be determined through the use of a competent model that has been accepted by the Florida Commission on Hurricane Loss Projection Methodology. A policy or program providing such coverage may not be issued or renewed after July 1, 2008, unless it has been reviewed and approved by the Office of Insurance Regulation. The review and approval must include approval of the policy and related forms pursuant to ss. [627.410](#) and [627.411](#), approval of the rates pursuant to s. [627.062](#), a determination that the loss model approved by the commission was accurately and appropriately applied to the insured structures to determine the 250-year probable maximum loss, and a determination that complete and accurate disclosure of all material provisions is provided to condominium unit owners before execution of the agreement by a condominium association.

3. When determining the adequate amount of property insurance coverage, the association may consider deductibles as determined by this subsection.

(b) If an association is a developer-controlled association, the association shall exercise its best efforts to obtain and maintain insurance as described in paragraph (a). Failure to obtain and maintain adequate property insurance during any period of developer control constitutes a breach of fiduciary responsibility by the developer-appointed members of the board of directors of the association, unless the members can show that despite such failure, they have made their best efforts to maintain the required coverage.

(c) Policies may include deductibles as determined by the board.

1. The deductibles must be consistent with industry standards and prevailing practice for communities of similar size and age, and having similar construction and facilities in the locale where the condominium property is situated.

2. The deductibles may be based upon available funds, including reserve accounts, or predetermined assessment authority at the time the insurance is obtained.

3. The board shall establish the amount of deductibles based upon the level of available funds and predetermined assessment authority at a meeting of the board in the manner set forth in s. [718.112\(2\)\(e\)](#).

(d) An association controlled by unit owners operating as a residential condominium shall use its best efforts to obtain and maintain adequate property insurance to protect the association, the association property, the common elements, and the condominium property that must be insured by the association pursuant to this subsection.

(e) The declaration of condominium as originally recorded, or as amended pursuant to procedures provided therein, may provide that condominium property consisting of freestanding buildings comprised of no more than one building in or on such unit need not be insured by the association if the declaration requires the unit owner to obtain adequate insurance for the condominium property. An association may also obtain and maintain liability insurance for directors and officers, insurance for the benefit of association employees, and flood insurance for common elements, association property, and units.

(f) Every property insurance policy issued or renewed on or after January 1, 2009, for the purpose of protecting the condominium must provide primary coverage for:

1. **All portions of the condominium property as originally installed or replacement of like kind and quality, in accordance with the original plans and specifications.**

2. All alterations or additions made to the condominium property or association property pursuant to s. [718.113\(2\)](#).

3. **The coverage must exclude all personal property within the unit or limited common elements, and floor, wall, and ceiling coverings, electrical fixtures, appliances, water heaters, water filters, built-in cabinets and countertops, and window treatments, including curtains, drapes, blinds, hardware, and similar window treatment components, or replacements of any of the foregoing which are located within the boundaries of the unit and serve only such unit.** Such property and any insurance thereupon is the responsibility of the unit owner.

(g) A condominium unit owner's policy must conform to the requirements of s. [627.714](#).

1. All reconstruction work after a property loss must be undertaken by the association except as otherwise authorized in this section. A unit owner may undertake reconstruction work on portions of the unit with the prior written consent of the board of administration. However, such work may be conditioned upon the approval of the repair methods, the qualifications of the proposed contractor, or the contract that is used for that purpose. A unit owner must obtain all required governmental permits and approvals before commencing reconstruction.

2. Unit owners are responsible for the cost of reconstruction of any portions of the condominium property for which the unit owner is required to carry property insurance, and any such reconstruction work undertaken by the association is chargeable to the unit owner and enforceable as an assessment pursuant to s. [718.116](#).

3. A multicondominium association may elect, by a majority vote of the collective members of the condominiums operated by the association, to operate the condominiums as a single condominium for purposes of insurance matters, including, but not limited to, the purchase of the property insurance required by this section and the apportionment of deductibles and damages in excess of coverage. The election to aggregate the treatment of insurance premiums, deductibles, and excess damages constitutes an amendment to the declaration of all condominiums operated by the association, and the costs of insurance must be stated in the association budget. The amendments must be recorded as required by s. [718.110](#).

(h) The association shall maintain insurance or fidelity bonding of all persons who control or disburse funds of the association. The insurance policy or fidelity bond must cover the maximum funds that will be in the custody of the association or its management agent at any one time. As used in this paragraph, the term "persons who control or disburse funds of the association" includes, but is not limited to, those individuals authorized to sign checks on behalf of the association, and the president, secretary, and treasurer of the association. The association shall bear the cost of any such bonding.

(i) The association may amend the declaration of condominium without regard to any requirement for approval by mortgagees of amendments affecting insurance requirements for the purpose of conforming the declaration of condominium to the coverage requirements of this subsection.

(j) Any portion of the condominium property that must be insured by the association against property loss pursuant to paragraph (f) which is damaged shall be reconstructed, repaired, or replaced as necessary by the association as a common expense. All property insurance deductibles, uninsured losses, and other damages in excess of property insurance coverage under the property insurance policies maintained by the association are a common expense of the condominium, except that:

1. A unit owner is responsible for the costs of repair or replacement of any portion of the condominium property not paid by insurance proceeds if such damage is caused by intentional conduct, negligence, or failure to comply with the terms of the declaration or the rules of the association by a unit owner, the members of his or her family, unit occupants, tenants, guests, or invitees, without compromise of the subrogation rights of the insurer.

2. The provisions of subparagraph 1. regarding the financial responsibility of a unit owner for the costs of repairing or replacing other portions of the condominium property also apply to the costs of repair or replacement of personal property of other unit owners or the association, as well as other property, whether real or personal, which the unit owners are required to insure.

3. To the extent the cost of repair or reconstruction for which the unit owner is responsible under this paragraph is reimbursed to the association by insurance proceeds, and the association has collected the cost of such repair or reconstruction from the unit owner, the association shall reimburse the unit owner without the waiver of any rights of subrogation.

4. The association is not obligated to pay for reconstruction or repairs of property losses as a common expense if the property losses were known or should have been known to a unit owner and were not reported to the association until after the insurance claim of the association for that property was settled or resolved with finality, or denied because it was untimely filed.

(k) An association may, upon the approval of a majority of the total voting interests in the association, opt out of the provisions of paragraph (j) for the allocation of repair or reconstruction expenses and allocate repair or reconstruction expenses in the manner provided in the declaration as originally recorded or as amended. Such vote may be approved by the voting interests of the association without regard to any mortgagee consent requirements.

(l) In a multicondominium association that has not consolidated its financial operations under subsection (6), any condominium operated by the association may opt out of the provisions of paragraph (j) with the approval of a majority of the total voting interests in that condominium. Such vote may be approved by the voting interests without regard to any mortgagee consent requirements.

(m) Any association or condominium voting to opt out of the guidelines for repair or reconstruction expenses as described in paragraph (j) must record a notice setting forth the date of the opt-out vote and the page of the official records book on which the declaration is recorded. The decision to opt out is effective upon the date of recording of the notice in the public records by the association. An association that has voted to opt out of paragraph (j) may reverse that decision by the same vote required in paragraphs (k) and (l), and notice thereof shall be recorded in the official records.

(n) The association is not obligated to pay for any reconstruction or repair expenses due to property loss to any improvements installed by a current or former owner of the unit or by the developer if the improvement benefits only the unit for which it was installed and is not part of the standard improvements installed by the developer on all units as part of original construction, whether or not such improvement is located within the unit. This paragraph does not relieve any party of its obligations regarding recovery due under any insurance implemented specifically for such improvements.

(o) The provisions of this subsection shall not apply to timeshare condominium associations. Insurance for timeshare condominium associations shall be maintained pursuant to s. [721.165](#).

Property & Wind Storm Insurance Liability Table

Identifies which party (Unit Owner or Association) is responsible for insurance coverage per State of Florida Statute 718

<u>BUILDING ELEMENT TO BE INSURED</u>	<u>UNIT OWNER</u>	<u>ASSOCIATION</u>
VERTICAL WALLS:		
Exterior:		
Mesh, Lath, Sheathing, Glass, Block, Stucco (Painted)		X
Studs & Insulation		X
Unfinished Sheet Rock (Drywall)		X
Interior Wall area of exterior wall (wall coverings)	X	
Interior Unit Walls (including party walls)		
Block, Studs & Insulation		X
Unfinished Sheet Rock (Drywall)		X
Interior Wall Treatments (paint, tile, wallpaper)	X	
Common Area Interior Walls		
Block, Studs & Insulation		X
Unfinished Sheet Rock (Drywall)		X
Interior Wall Treatments (paint, tile, wallpaper)		X
HORIZONTAL WALLS (including ceilings):		
Interior Unit Floors		
Concrete, Framing, Insulation, Plywood.		X
Floor Coverings	X	
Common Area Floors		
Concrete, Framing, Insulation, Plywood.		X
Floor Coverings		X
Interior Unit Ceilings & Roof Area		
Concrete, Framing, Plywood, Insulation, Sheet rock		X
Paint and/or Texture Finish (popcorn, spackling, etc)	X	
Common Area Ceilings & Roof Area		
Concrete, Framing, Plywood, Insulation, Sheet rock		X
Paint and/or Texture Finish (popcorn, spackling, etc)		X
ROOFING (interior units & common areas):		
All Framing, Supports, Deckings, Insulation & Covering		X
UNIT INTERIOR FINISHES:		
Electrical Fixtures, Appliances, Air Handlers, Water Heaters & Cabinets	X	

Flood Insurance Liability Table

Identifies which party (Unit Owner or Association) is responsible for flood insurance coverage per the National Flood Insurance Program guidelines.

<u>BUILDING ELEMENT TO BE INSURED</u>	<u>UNIT OWNER</u>	<u>ASSOCIATION</u>
VERTICAL WALLS:		
Exterior:		
Mesh, Lath, Sheathing, Glass, Block, Stucco (Painted)		X
Studs & Insulation		X
Unfinished Sheet Rock (Drywall)		X
Interior Wall area of exterior wall (wall coverings)		X
Interior Unit Walls (including party walls)		
Block, Studs & Insulation		X
Unfinished Sheet Rock (Drywall)		X
Interior Wall Treatments (paint, tile, wallpaper)		X
Common Area Interior Walls		
Block, Studs & Insulation		X
Unfinished Sheet Rock (Drywall)		X
Interior Wall Treatments (paint, tile, wallpaper)		X
HORIZONTAL WALLS (including ceilings):		
Interior Unit Floors		
Concrete, Framing, Insulation, Plywood.		X
Floor Coverings		X
Common Area Floors		
Concrete, Framing, Insulation, Plywood.		X
Floor Coverings		X
Interior Unit Ceilings & Roof Area		
Concrete, Framing, Plywood, Insulation, Sheet rock		X
Paint and/or Texture Finish (popcorn, spackling, etc)		X
Common Area Ceilings & Roof Area		
Concrete, Framing, Plywood, Insulation, Sheet rock		X
Paint and/or Texture Finish (popcorn, spackling, etc)		X
ROOFING (interior units & common areas):		
All Framing, Supports, Deckings, Insulation & Covering		X
UNIT INTERIOR FINISHES:		
Electrical Fixtures, Appliances, Air Handlers, Water Heaters & Cabinets		X

About Expert Inspectors , Inc.

Expert Inspectors has been conducting replacement cost valuations (insurance appraisals) since 2002. We are and have always been a family owned and operated company. We pride ourselves on offering the very best professional and personalized service to our client associations. Over the years Expert has had the honor to service the needs of thousands of associations, homeowners & commercial property owners.

Expert Inspectors is fully licensed and insured. All of our personnel are highly trained and fully certified for the duties that they perform.

Dave Kolodzik, PPIA, CRVS President



Dave Kolodzik has been conducting Replacement Cost Valuations on associations since 2002. He has completed literally thousands of Insurance Appraisals for commercial buildings, homes as well as condominium & homeowner associations.

Dave is a former licensed All-Lines Insurance Adjuster with the PPIA (Professional Property Insurance Adjuster) designation as well as a Certified Replacement Valuation Specialist (CRVS). He is also certified by the State of Florida as a Continuing Education Provider teaching Replacement Cost Valuation classes.

All aspects of every replacement cost valuation conducted by Expert Inspectors are personally conducted or supervised by Dave. No large international corporate atmosphere. No boiler plated one size fits all inspection and valuation. We offer our clients true individual professional and personal service. Every replacement cost valuation is produced to the individual needs of the each association.

Client Promise

Expert Inspectors takes our commitment seriously & appreciates the confidence and faith that our clients place in us. To that end we make the following promise:

1. We will strive to provide you with the professional and personalized service that you deserve at a competitive price.
2. The on-site Specialist will be the person who processes your report. No having to deal with several different people who ask you the same questions over and over.
3. The Specialist who is assigned to your Association will be thoroughly trained and certified to conduct both the on-site visit as well as process your report.
4. All emails and phone calls will be returned within one (1) business day by either the Specialist assigned to you or by a corporate officer of Expert Inspectors. Our clients are far too important to have their questions or concerns put off or ignored. We will make sure the person who contacts you back will either have an answer for you or will be in a position to provide you with one quickly.



The Power of
PROPERTY INTELLIGENCE

Certificate Of Award

THIS IS TO CERTIFY THAT

David E. Kolodzik

Has Been Awarded The Designation Of

Certified Replacement Valuation Specialist (CRVS)

In The Following Categories

Commercial
Building Valuation System (BVS)

Residential
Residential Component Technology (RCT)
Residential Component Technology High Value (RCT-HV)

January 22, 2012

Issued by Marshall & Swift / Boeckh (MSB)



Certificate of Completion

This certifies that the named person has successfully completed the insurance course taught in compliance with the rules of Florida Department of Financial Services.

David Kolodzik

has been awarded the PPIA designation and has successfully completed the following course offered by HurriClaim Training Academy, in partnership with MindCross Training.

*Professional Property Insurance Adjuster (PPIA)
Designation Course*

Completion Date: May 5th, 2018


Rosanne Hutton
School Official

May 07, 2018
Date

HurriClaim

mindcross
training services

Certificate Details

Provider: HurriClaim Training

Course ID: 95344

Offering ID: 1079476

www.mindcross.com
www.wetrainadjusters.com
training@mindcross.com
304.725.2617